HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS CAL, 19-LOSAN, 67-

HABS No. CA-1987

Richfield Oil Building 555 S. Flower Street Los Angeles Los Angeles County California

Marvin Rand, Photographer, 1968

CA-1987-1	EXTERIOR, GENERAL VIEW FROM NORTH
CA-1987-2	EXTERIOR, NORTH SIDE AND EAST FRONT
CA-1987-3	EXTERIOR, NORTH AND WEST SIDES
CA-1987-4	EXTERIOR, WEST SIDE
CA-1987-5	EXTERIOR, COURTYARD VIEW, LOOKING FROM THE GROUND UP
CA-1987-6	EXTERIOR, NORTH SIDE SHOWING GARAGE RAMP
CA-1987-7	EXTERIOR, NORTH SIDE SHOWING OFFICE FLOORS
CA-1987-8	EXTERIOR, NORTH SIDE DETAIL OF UPPER FLOORS
CA-1987-9	EXTERIOR, EAST FRONT, SHOWING OFFICE FLOORS
CA-1987-10	EXTERIOR, EAST FRONT, DETAIL OF WINDOWS AND FIRE ESCAPE
CA-1987-11	EXTERIOR, EAST FRONT, SIDE VIEW OF FIRE ESCAPE
CA-1987 <u></u> 12	EXTERIOR, EAST ENTRANCE SHOWING TERRA COTTA FIGURES
CA-1987-13	EXTERIOR, EAST ENTRANCE SHOWING ARCHED OPENING BELOW TERRA COTTA FIGURES
CA-1987-14	EXTERIOR, EAST ENTRANCE, CLOSE-UP OF TWO TERRA COTTA FIGURES
CA-1987-15	EXTERIOR, EAST ENTRANCE, DOORWAY
CA-1987-16	EXTERIOR, EAST ENTRANCE, FROM OUTSIDE LOOKING IN TOWARD LOBBY
CA-1987-17	EXTERIOR, EAST ENTRANCE SHOWING EXTERIOR WINDOWS AND STREET ADDRESS "555"
CA-1987-18	EXTERIOR, NAMEPLATE DETAIL NEAR EAST ENTRANCE
CA-1987-19	EXTERIOR, DETAIL OF UPPER FLOORS WITH TERRA COTTA FIGURES
CA-1987-20	EXTERIOR, DETAIL OF SCULPTURED FIGURES ON UPPER FLOORS

CA-1987-21	EXTERIOR, DETAIL OF HEAD OF FIGURE, SIDE VIEW, UPPER FLOORS
CA-1987-22	EXTERIOR, CORNER VIEW OF TWO TERRA COTTA FIGURES, UPPER FLOORS
CA-1987-23	INTERIOR, VIEW OF LOBBY AT EAST ENTRANCE
CA-1987-24	INTERIOR, LOBBY, STAIRWAY DOOR
CA-1987-25	INTERIOR, LOBBY, MAILBOX NEAR ELEVATORS
CA-1987-26	INTERIOR, LOBBY, ELEVATOR DOORS, MASTER CONTROL PANEL
CA-1987-27	INTERIOR, LOBBY, ELEVATOR CONTROL PANEL, SIDE VIEW
CA-1987-28	INTERIOR, CLOSE-UP OF ELEVATOR CONTROL PANEL, FRONT VIEW
CA-1987-29	INTERIOR, ELEVATOR DOOR SHOWING ORNAMENTATION
CA-1987-30	INTERIOR, DETAIL OF ABSTRACT CAST BRONZE ORNAMENTATION ON ELEVATOR DOORS
CA-1987-31	INTERIOR, CLOSE-UP OF ELEVATOR DOOR ORNAMENTATION
CA-1987-32	INTERIOR, DETAIL OF ETCHED PATTERN IN STONE NEAR ELEVATOR DOORS, LOBBY
CA-1987-33	INTERIOR, ELABORATE CARVED PLASTER CEILING, LOBBY
CA-1987-34	INTERIOR, DETAIL OF CEILING ORNAMENTATION, LOBBY
CA-1987-35	INTERIOR, DETAIL OF WINDOW NEAR ELEVATORS, LOBBY
CA-1987-36	INTERIOR, BRONZE PLAQUE IN FLOOR OF STREET LEVEL LOBBY
CA-1987-37	INTERIOR, NAME OF BUILDING IN BRONZE, FIRST FLOOR LOBBY
CA-1987-38	INTERIOR, UPPER FLOOR ELEVATORS
CA-1987-39	INTERIOR, UPPER FLOOR ELEVATOR DOORS
CA-1987-40	INTERIOR, STAIRWAY
CA-1987-41	INTERIOR, STAIR AND LANDING
CA-1987-42	INTERIOR, CLOSE-UP OF DOOR KNOB
CA-1987-43	INTERIOR, WASHROOM SHOWING SINKS
CA-1987-44	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown FIRST FLOOR PLAN

CA-1987-45	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown SECOND FLOOR PLAN
CA-1987-46	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown NORTH ELEVATION
CA-1987-47	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angleles, CA, Photographer, Date unknown WEST ELEVATION
CA-1987-48	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA., Photographer, Date unknown SECTION THROUGH BUILDING, LOOKING NORTH
CA-1987-49	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown SECTION THROUGH BUILDING, LOOKING EAST
CA-1987-50	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angleles, CA, Photographer, Date unknown ENTRANCE AND TYPICAL BAY ON FLOWER STREET
CA-1987-51	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown EXTERIOR, ELEVATION DETAILS
CA-1987-52	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown DETAILS OF MAIN FLOOR ELEVATOR LOBBY
CA-1987-53	Photocopy of drawing (Source unknown, 1928) Rapid Blue Print Co., Los Angeles, CA, Photographer, Date unknown DETAILS OF CORRIDORS ON SECOND - TWELFTH FLOORS

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS CAL, 19-LOSAN, 67-

Addendum to Richfield Oil Building 555 S. Flower Street Los Angeles Los Angeles County California

HABS No. CA-1987

Photographs no. CA-1987-1 through CA-1987-53 previously transmitted to Library of Congress. The following photographs document the demolition of the building.

Marvin Rand,	photographer April 1969
CA-1987-54	NORTH SIDE AND EAST FRONT DURING DEMOLITION, DISTANT VIEW
CA~1987-55	NORTH SIDE AND EAST FRONT DURING DEMOLITION, CLOSE VIEW
CA-1987-56	WEST SIDE DURING DEMOLITION, DISTANT VIEW
CA~1987-57	WEST SIDE DURING DEMOLITION, CLOSE VIEW
CA-1987-58	REAR VIEW DURING DEMOLITION
CA-1987-59	GENERAL VIEW DURING DEMOLITION, WITH SCAFFOLDING